PALM INTRANET

Day: Thursday Date: 6/29/2006

Time: 14:20:24

Inventor Name Search Result

Your Search was:

Last Name = ELZUR

First Name = URI

	.	G	D . D . D		
Application#	Patent#	=			Inventor Name
<u>09364085</u>	Not Issued	135	07/30/1999	ASSOCIATING A PACKET WITH A FLOW	ELZUR, URI
<u>09364096</u>	6427169	150	07/30/1999	PARSING A PACKET HEADER	ELZUR, URI
09364195	Not Issued	41	07/30/1999	COORDINATING AUTHENTICATION AND ENCRYPTION/DECRYPTION	ELZUR, URI
09364374	6449656	150	07/30/1999	STORING A FRAME HEADER	ELZUR, URI
09364826	Not Issued	71	07/30/1999	A system and technique to process secured services for data in a network	ELZUR, URI
09364835	Not Issued	123	07/30/1999	TECHNIQUE AND APPARATUS FOR PROCESSING CRYPTOGRAPHIC SERVICES OF DATA IN A NETWORK SYSTEM	ELZUR, URI
09365328	6728265	150	07/30/1999	CONTROLLING FRAME TRANSMISSION	ELZUR, URI
09365329	Not Issued	161	07/30/1999	STORING PACKET DATA	ELZUR, URI
<u>09677139</u>	Not Issued	160	09/29/2000	Computer telephony integration adapter	ELZUR, URI
09772732	6621893	150		COMPUTER TELEPHONY INTEGRATION ADAPTER	ELZUR, URI
10100212	6906978	150		FLEXIBLE INTEGRATED MEMORY	ELZUR, URI
10173422	Not Issued	41		Multiple virtual channels for use in network devices	ELZUR, URI
10188377	6629125	150	07/02/2002	STORING A FRAME HEADER	ELZUR, URI
10188378	6629141	150	07/02/2002	STORING A FRAME HEADER	ELZUR, URI
<u></u>					

10230643	Not Issued	71	08/29/2002	System and method for identifying upper layer protocol message boundaries	ELZUR, URI
10331302	Not Issued	30	12/30/2002	Receiver-aided set-up request routing	ELZUR, URI
10377833	Not Issued	30	03/03/2003	System and method for expediting upper layer protocol (ULP) connection negotiations	ELZUR, URI
10642023	Not Issued	41	08/14/2003	One shot RDMA having a 2-bit state	ELZUR, URI
10643331	Not Issued	30	08/19/2003	One-shot RDMA	ELZUR, URI
10651459	Not Issued	120	08/29/2003	System and method for handling out- of-order frames	ELZUR, URI
10652183	Not Issued	71	08/29/2003	System and method for TCP/IP offload independent of bandwidth delay product	ELZUR, URI
10652267	Not Issued	122	08/29/2003	System and method for TCP offload	ELZUR, URI
10652270	Not Issued	30	08/29/2003	Method and system for data placement of out-of-order (OOO) TCP segments	ELZUR, URI
10652327	Not Issued	30	08/29/2003	System and method for network interfacing in a multiple network environment	ELZUR, URI
10652330	Not Issued	30	08/29/2003	System and method for network interfacing	ELZUR, URI
10688373	Not Issued	30		System and method for receive queue provisioning	ELZUR, URI
10688392	Not Issued	30	10/17/2003	System and method for receive queue provisioning	ELZUR, URI
10704891	Not Issued	71	11/10/2003	System and method for managing memory	ELZUR, URI
10727430	Not Issued	30	12/04/2003	Data path security processing	ELZUR, URI
10751732	Not Issued	30	01/02/2004	System and method for handling transport protocol segments	ELZUR, URI
10803719	Not Issued	30		Self-describing transport protocol segments	ELZUR, URI
10938156	Not Issued	20	09/10/2004	System and method for load balancing and fail over	ELZUR, URI
11126464	Not Issued	30		Method and system for handling out- of-order segments in a wireless system via direct data placement	ELZUR, URI

11126565	Not Issued	160	05/11/2005	Method and system for wireless transmission control protocol offload engine	ELZUR, URI
11126822	Not Issued	160	05/11/2005	Method and system for processing data segments on-the-fly	ELZUR, URI
<u>11128056</u>	Not Issued	160	05/11/2005	Method and system for controlling offload of connections in a wireless data network	ELZUR, URI
11128065	Not Issued	160	05/11/2005	Method and system for power management during TCP offload	ELZUR, URI
11128071	Not Issued	160	05/11/2005	Method and system for transferring state information during wireless handoff	ELZUR, URI
11253429	Not Issued	19	10/18/2005	Network interface device serving multiple host operating systems	ELZUR, URI
11416717	Not Issued	20	05/03/2006	Network interface device serving multiple host operating systems	ELZUR, URI
60306870	Not Issued	159	07/23/2001	Selective flow control based on multiple virtual channels	ELZUR, URI
60362531	Not Issued	159	03/07/2002	Method of RDMA connection negotiation	ELZUR, URI
60362554	Not Issued	159	03/07/2002	Receiver-aided set-up request routing	ELZUR, URI
60363356	Not Issued	159	03/11/2002	Method of identifying ULP header in TCP stream	ELZUR, URI
60363381	Not Issued	159	03/08/2002	Method of identifying ULP header in TCP stream	ELZUR, URI
60372851	Not Issued	159	III I	Method for marker based re- segmentation detection	ELZUR, URI
60372852	Not Issued	159	04/16/2002	Method for marker based resegmentation detection	ELZUR, URI
60403817	Not Issued	159	08/14/2002	One shot RDMA having only a 2 bit state	ELZUR, URI
60404709	Not Issued	159	08/19/2002	Optimizing RDMA for storage applications	ELZUR, URI
60407165	Not Issued	159	08/30/2002	System and method for TCP offload	ELZUR, URI

Search and Display More Records.

Search Another: Inven	Last Nan	ne First Name	
Scarch Another, inven	ELZUR	URI	Search

To go back use Back button on your browser toolbar.